**FIG. 1**

+

2/6

0	0	0	0	0	0	2	2	2
0	0	0	0	0	2	2	2	2
0	0	0	0	0	2	2	2	2
0	0	0	0	2	2	2	2	2
0	0	0	0	2	2	2	2	2
0	0	0	0	2	2	2	2	2
0	0	0	0	2	2	2	2	2
0	0	0	0	0	2	2	2	2

FIG. 2A

0	0	0	0	0	1	2	2	2
0	0	0	0	0	1	2	2	2
0	0	0	0	1	2	2	2	2
0	0	0	0	1	2	2	2	2
0	0	0	1	1	2	2	2	2
0	0	0	1	1	2	2	2	2
0	0	0	0	1	2	2	2	2
0	0	0	0	1	2	2	2	2

FIG. 2B

+

+

3/6

0	0	0	0	0	1	2	2	2
0	0	0	0	0	1	2	2	2
0	0	0	0	1	2	2	2	2
0	0	0	0	1	2	2	2	2
0	0	0	1	1	2	2	2	2
0	0	0	1	1	2	2	2	2
0	0	0	0	1	2	2	2	2
0	0	0	0	1	2	2	2	2

FIG. 2C

32	32	32	32	32	2	30	30	30
32	32	32	32	32	2	30	30	30
32	32	32	32	8	30	30	30	30
32	32	32	32	8	30	30	30	30
32	32	32	8	8	30	30	30	30
32	32	32	8	8	30	30	30	30
32	32	32	32	8	30	30	30	30
32	32	32	32	8	30	30	30	30

FIG. 2D

+

+

4/6




FIG. 3A




FIG. 3B

+

+

5/6



FIG. 4




FIG. 5




FIG. 6




FIG. 7

+

+

6/6



FIG. 8




FIG. 9A




FIG. 9B




FIG. 9C

+